

Property Damage Assessment Report

Client: Demo data - privacy protected · Storm damage claim assessment

Visit Date: 28 September 2026, 10:00 AM – 11:10 AM

Generated by: AI report assistant, from a Preserver field export

Summary

A property damage assessment was carried out following a storm event, covering a roof and tile damage inspection, a vehicle panel damage assessment, and claim documentation sign-off. All observations were captured on-site using the Preserver app, with GPS location and timestamp data recorded automatically alongside supporting photos and voice notes converted to text.

Roof tiles and flashing showed clear storm damage consistent with the claim description, vehicle panel damage was assessed and photographed for the claim file, and the assessment checklist was completed and signed off on-site.

Assessment Summary

Category	Observation	Status	Action Required
Roof Damage	Tile and flashing damage consistent with claim	Complete	Forward to claims processing
Vehicle Damage	Panel dent assessed and photographed	Complete	None
Claim Documentation	Checklist completed and signed off	Complete	None

Field Evidence

The following images and captions were captured directly through the Preserver app during the visit. Each entry retains its original GPS coordinates and capture timestamp. Demo data - privacy protected.



Roof — storm damage inspection

-27.4801, 153.0312 · 28 Sep 2026, 10:12 AM

Roof tiles and flashing inspected, damage consistent with the storm event described in the claim.



Vehicle — panel damage assessment

-27.4801, 153.0312 · 28 Sep 2026, 10:38 AM

Vehicle panel damage assessed and photographed close-up for the claim file.



Claim documentation — checklist sign-off

-27.4801, 153.0312 · 28 Sep 2026, 11:00 AM

Assessment checklist completed and signed off on-site as part of the claim record.

Voice & Text Observations

Observations below were recorded on-site as voice notes and automatically transcribed, or entered directly as text, through the Preserver app.

Time	Type	Transcript / Note
10:12 AM	Voice	"Roof's showing clear storm damage, tiles and flashing both affected, consistent with what's described in the claim."
10:38 AM	Voice	"Got the panel damage photographed close-up, that's going straight into the claim file."
11:00 AM	Text	Assessment checklist completed and signed off on-site.

Site Visit Log

10:00 AM	Activity started on-site — GPS lock confirmed, property location
10:12 AM	Roof damage inspection — photo + voice observation logged
10:38 AM	Vehicle damage assessment — photo + voice observation logged
11:00 AM	Claim documentation — photo + text observation logged
11:10 AM	Activity ended and locked — record sealed, tamper-evident

How This Report Was Produced

This report was generated from a single Preserver export — no re-typing, no separate note-taking app, and no manual GPS lookups. During the visit, every photo, voice note and text entry was captured in one place, each automatically stamped with the time and exact location it was recorded.

At the end of the visit, the activity was locked directly in the app, sealing the record so nothing could be altered after the fact. The full activity — photos, transcripts, GPS log and metadata — was then exported in one step (JSON + Photos) and handed to an AI assistant, which produced the structured report above in a matter of minutes.

The result: a defensible, timestamped, location-verified record of the assessment, turned into a claims-ready report the same day it was captured.

Preserver

Free to capture. Record your observations — photo, video, voice or text — with GPS and timestamp on every entry. Export anywhere, including straight to AI. preserver.me