

Painting Job Report

Client: Demo data - privacy protected · Residential repaint
Visit Date: 28 September 2026, 7:30 AM – 3:30 PM
Generated by: AI report assistant, from a Preserver field export

Summary

A residential interior and exterior repaint job was carried out at the property, covering the living room wall finish, exterior window frame preparation, and final material/checklist sign-off. All observations were captured on-site using the Preserver app, with GPS location and timestamp data recorded automatically alongside supporting photos and voice notes converted to text.

The living room wall was completed to two coats as specified, the exterior window frames required extra scraping and priming before painting due to old peeling paint, and all materials and colors were confirmed against the job sheet at close-out.

Job Summary

Category	Observation	Status	Action Required
Interior Wall Finish	Living room, two coats applied, clean lines	Complete	None
Exterior Prep	Window frames needed extra scraping and priming	Attention	Allow extra dry time before coat 2
Materials Check	Paint colors and quantities match job sheet	On Track	None

Field Evidence

The following images and captions were captured directly through the Preserver app during the visit. Each entry retains its original GPS coordinates and capture timestamp. Demo data - privacy protected.



Living room — wall finish

-27.4712, 153.0281 · 28 Sep 2026, 9:15 AM

Two coats applied to the living room wall, clean edges along the trim line.



Exterior window frame — before prep

-27.4712, 153.0282 · 28 Sep 2026, 11:02 AM

Old peeling paint on the exterior window frame, requiring extra scraping and priming before top coat.



Job close-out — materials check

-27.4711, 153.0280 · 28 Sep 2026, 3:20 PM

Paint cans and color swatches checked off against the job sheet at close-out.

Voice & Text Observations

Observations below were recorded on-site as voice notes and automatically transcribed, or entered directly as text, through the Preserver app.

Time	Type	Transcript / Note
9:15 AM	Voice	"Living room's done, second coat's on and it's looking even, no patchy spots."
11:02 AM	Voice	"Window frames out front are worse than expected, old paint's peeling right back — need to scrape and prime before we go again."
3:20 PM	Text	Materials and colors checked against job sheet at close-out, all matched.

Site Visit Log

7:30 AM	Activity started on-site — GPS lock confirmed, property address
9:15 AM	Living room wall — photo + voice observation logged
11:02 AM	Exterior window frames — photo + voice observation logged
3:20 PM	Materials check — photo + text observation logged
3:30 PM	Activity ended and locked — record sealed, tamper-evident

How This Report Was Produced

This report was generated from a single Preserver export — no re-typing, no separate note-taking app, and no manual GPS lookups. During the visit, every photo, voice note and text entry was captured in one place, each automatically stamped with the time and exact location it was recorded.

At the end of the visit, the activity was locked directly in the app, sealing the record so nothing could be altered after the fact. The full activity — photos, transcripts, GPS log and metadata — was then exported in one step (JSON + Photos) and handed to an AI assistant, which produced the structured report above in a matter of minutes.

The result: a defensible, timestamped, location-verified record of the job, turned into a client-ready report the same day it was captured.

Preserver

Free to capture. Record your observations — photo, video, voice or text — with GPS and timestamp on every entry. Export anywhere, including straight to AI. preserver.me