

Vehicle Recovery Job Report

Client: Demo data - privacy protected · Roadside recovery job

Visit Date: 28 September 2026, 5:50 PM – 6:35 PM

Generated by: AI report assistant, from a Preserver field export

Summary

A roadside vehicle recovery job was carried out on the highway shoulder, covering the vehicle condition at pickup, a pre-tow dashboard check, and job paperwork sign-off. All observations were captured on-site using the Preserver app, with GPS location and timestamp data recorded automatically alongside supporting photos and voice notes converted to text.

The vehicle was safely winched onto the flatbed with no additional damage caused during loading, the dashboard and odometer were photographed for a pre-tow condition record, and job paperwork was completed and signed off at the drop-off point.

Job Summary

Category	Observation	Status	Action Required
Vehicle Loading	Winched onto flatbed, no additional damage caused	Complete	None
Pre-Tow Condition	Dashboard and odometer photographed before transport	Complete	None
Job Paperwork	Recovery docket signed off at drop-off	Complete	None

Field Evidence

The following images and captions were captured directly through the Preserver app during the visit. Each entry retains its original GPS coordinates and capture timestamp. Demo data - privacy protected.



Roadside recovery — vehicle loading

-27.4321, 153.0512 · 28 Sep 2026, 5:58 PM

Damaged sedan winched onto the flatbed tray from the highway shoulder, hazard lights active throughout.



Pre-tow condition — dashboard check

-27.4321, 153.0512 · 28 Sep 2026, 6:05 PM

Dashboard and odometer photographed to record pre-tow vehicle condition.



Job close-out — recovery docket

-27.4298, 153.0489 · 28 Sep 2026, 6:30 PM

Recovery job docket completed and signed off at the drop-off yard.

Voice & Text Observations

Observations below were recorded on-site as voice notes and automatically transcribed, or entered directly as text, through the Preserver app.

Time	Type	Transcript / Note
5:58 PM	Voice	"Vehicle's loaded up, winch went smooth, no extra damage from the recovery itself."
6:05 PM	Voice	"Got the dash and odometer photographed before we head off, just for the record."
6:30 PM	Text	Recovery docket signed off at drop-off, job complete.

Site Visit Log

5:50 PM	Activity started on-site — GPS lock confirmed, highway shoulder location
5:58 PM	Vehicle loading — photo + voice observation logged
6:05 PM	Pre-tow condition check — photo + voice observation logged
6:30 PM	Job paperwork — photo + text observation logged
6:35 PM	Activity ended and locked — record sealed, tamper-evident

How This Report Was Produced

This report was generated from a single Preserver export — no re-typing, no separate note-taking app, and no manual GPS lookups. During the visit, every photo, voice note and text entry was captured in one place, each automatically stamped with the time and exact location it was recorded.

At the end of the visit, the activity was locked directly in the app, sealing the record so nothing could be altered after the fact. The full activity — photos, transcripts, GPS log and metadata — was then exported in one step (JSON + Photos) and handed to an AI assistant, which produced the structured report above in a matter of minutes.

The result: a defensible, timestamped, location-verified record of the recovery job, turned into a client-ready report the same day it was captured.

Preserver

Free to capture. Record your observations — photo, video, voice or text — with GPS and timestamp on every entry. Export anywhere, including straight to AI. preserver.me