

Site Progress Inspection Report

Client: Demo data - privacy protected · New build progress inspection

Visit Date: 28 September 2026, 8:30 AM – 9:12 AM

Generated by: AI report assistant, from a Preserver field export

Summary

A scheduled progress inspection was carried out at the build site, covering wall framing status, foundation condition, and general site compliance. All observations were captured on-site using the Preserver app, with GPS location and timestamp data recorded automatically alongside supporting photos and voice notes converted to text.

Wall framing is progressing on schedule and matches the approved plans, a minor hairline crack was noted in the foundation slab that falls within normal tolerance but has been logged for the file, and the site checklist confirmed materials and safety compliance are in order.

Inspection Summary

Category	Observation	Status	Action Required
Wall Framing	Framing on schedule, matches approved plans	OK	No action required
Foundation	Hairline crack in slab, within normal tolerance	Monitor	Note for file, recheck next visit
Site Compliance	Materials and safety checklist confirmed	OK	No action required

Field Evidence

The following images and captions were captured directly through the Preserver app during the visit. Each entry retains its original GPS coordinates and capture timestamp. Demo data - privacy protected.



Wall framing — progress view

-27.4622, 152.9967 · 28 Sep 2026, 8:34 AM

Timber wall framing progressing on schedule and consistent with the approved building plans.



Foundation slab — crack inspection

-27.4623, 152.9968 · 28 Sep 2026, 8:51 AM

Hairline crack measured across the foundation slab, assessed as within normal tolerance.



Field tablet — site checklist

-27.4622, 152.9966 · 28 Sep 2026, 9:05 AM

On-device checklist confirming materials and safety compliance for the site visit.

Voice & Text Observations

Observations below were recorded on-site as voice notes and automatically transcribed, or entered directly as text, through the Preserver app.

Time	Type	Transcript / Note
8:34 AM	Voice	"Framing's looking good, right on schedule and matching what's on the plans. No issues to flag here."
8:51 AM	Voice	"There's a hairline crack in the slab here, measured it and it's within normal tolerance, but I'll note it for the file just in case."
9:05 AM	Text	Site checklist reviewed — materials and safety compliance confirmed, no outstanding items.

Site Visit Log

8:30 AM	Activity started on-site — GPS lock confirmed, build site
8:34 AM	Wall framing — photo + voice observation logged
8:51 AM	Foundation — photo + voice observation logged
9:05 AM	Site checklist — photo + text observation logged
9:12 AM	Activity ended and locked — record sealed, tamper-evident

How This Report Was Produced

This report was generated from a single Preserver export — no re-typing, no separate note-taking app, and no manual GPS lookups. During the visit, every photo, voice note and text entry was captured in one place, each automatically stamped with the time and exact location it was recorded.

At the end of the visit, the activity was locked directly in the app, sealing the record so nothing could be altered after the fact. The full activity — photos, transcripts, GPS log and metadata — was then exported in one step (JSON + Photos) and handed to an AI assistant, which produced the structured report above in a matter of minutes.

The result: a defensible, timestamped, location-verified record of the inspection, turned into a client-ready progress report the same day it was captured.

Preserver

Free to capture. Record your observations — photo, video, voice or text — with GPS and timestamp on every entry. Export anywhere, including straight to AI. preserver.me