

# Vehicle Service Report

Client: Demo data - privacy protected · Scheduled service visit

Visit Date: 28 September 2026, 10:00 AM – 11:15 AM

Generated by: AI report assistant, from a Preserver field export

## Summary

A scheduled vehicle service was carried out at the workshop, covering an engine bay inspection, a brake component check, and diagnostic sign-off against the service checklist. All observations were captured on-site using the Preserver app, with GPS location and timestamp data recorded automatically alongside supporting photos and voice notes converted to text.

The engine bay showed no fluid leaks or worn belts, the front brake pads were found close to minimum thickness and flagged for replacement at the next visit, and the diagnostic scan returned no active fault codes.

## Service Summary

| Category           | Observation                     | Status    | Action Required         |
|--------------------|---------------------------------|-----------|-------------------------|
| Engine Bay         | No leaks or worn belts observed | On Track  | None                    |
| Brake Pads (Front) | Pad thickness close to minimum  | Attention | Replace at next service |
| Diagnostic Scan    | No active fault codes returned  | On Track  | None                    |

## Field Evidence

The following images and captions were captured directly through the Preserver app during the visit. Each entry retains its original GPS coordinates and capture timestamp. Demo data - privacy protected.



### ***Engine bay — inspection***

-27.4650, 153.0198 · 28 Sep 2026, 10:08 AM

Engine bay inspected on the hoist, no fluid leaks or worn belts observed.



### ***Front brake pad — wear check***

-27.4650, 153.0198 · 28 Sep 2026, 10:32 AM

Front brake pad and rotor removed for inspection, pad thickness close to minimum and flagged for replacement.



### ***Service checklist — diagnostic sign-off***

-27.4649, 153.0197 · 28 Sep 2026, 11:10 AM

Diagnostic scan tool results checked off against the service checklist, no active fault codes.

## Voice & Text Observations

Observations below were recorded on-site as voice notes and automatically transcribed, or entered directly as text, through the Preserver app.

| Time     | Type  | Transcript / Note                                                                                                 |
|----------|-------|-------------------------------------------------------------------------------------------------------------------|
| 10:08 AM | Voice | "Engine bay's clean, no leaks, belts all look tight and in good condition."                                       |
| 10:32 AM | Voice | "Front pads are getting close to minimum thickness — still safe for now but worth flagging for the next service." |
| 11:10 AM | Text  | Diagnostic scan complete, no active fault codes returned.                                                         |

## Site Visit Log

|          |                                                                 |
|----------|-----------------------------------------------------------------|
| 10:00 AM | Activity started on-site — GPS lock confirmed, workshop address |
| 10:08 AM | Engine bay inspection — photo + voice observation logged        |
| 10:32 AM | Brake pad check — photo + voice observation logged              |
| 11:10 AM | Diagnostic sign-off — photo + text observation logged           |
| 11:15 AM | Activity ended and locked — record sealed, tamper-evident       |

## How This Report Was Produced

This report was generated from a single Preserver export — no re-typing, no separate note-taking app, and no manual GPS lookups. During the visit, every photo, voice note and text entry was captured in one place, each automatically stamped with the time and exact location it was recorded.

At the end of the visit, the activity was locked directly in the app, sealing the record so nothing could be altered after the fact. The full activity — photos, transcripts, GPS log and metadata — was then exported in one step (JSON + Photos) and handed to an AI assistant, which produced the structured report above in a matter of minutes.

The result: a defensible, timestamped, location-verified record of the service, turned into a client-ready report the same day it was captured.

---

### Preserver

Free to capture. Record your observations — photo, video, voice or text — with GPS and timestamp on every entry. Export anywhere, including straight to AI. [preserver.me](https://preserver.me)