

Property Condition Inspection Report

Client: Demo data - privacy protected · Routine tenancy inspection

Visit Date: 28 September 2026, 11:00 AM – 11:34 AM

Generated by: AI report assistant, from a Preserver field export

Summary

A routine property condition inspection was carried out at the tenanted unit, covering ceiling and wall condition, kitchen fixtures and cabinetry, and a general walkthrough checklist. All observations were captured on-site using the Preserver app, with GPS location and timestamp data recorded automatically alongside supporting photos and voice notes converted to text.

A water stain with minor mould spotting was found on a ceiling corner, likely linked to a past minor leak, and a kitchen cabinet hinge was noted as loose. Neither issue is urgent, but both have been logged for the property file with recommended maintenance follow-up.

Inspection Summary

Category	Observation	Status	Action Required
Ceiling & Walls	Water stain and minor mould spotting, ceiling corner	Attention	Schedule maintenance check
Kitchen	Loose cabinet hinge, otherwise good condition	Monitor	Tighten hinge next visit
General Condition	Remaining rooms and fixtures in good order	OK	No action required

Field Evidence

The following images and captions were captured directly through the Preserver app during the visit. Each entry retains its original GPS coordinates and capture timestamp. Demo data - privacy protected.



Ceiling corner — water stain

-27.4703, 152.9812 · 28 Sep 2026, 11:05 AM

Water stain with minor mould spotting on the bedroom ceiling corner, consistent with a past minor leak.



Kitchen cabinetry — condition check

-27.4704, 152.9813 · 28 Sep 2026, 11:18 AM

Kitchen cabinet and appliance area showing a loose hinge; overall condition otherwise good.



Field tablet — inspection checklist

-27.4703, 152.9811 · 28 Sep 2026, 11:28 AM

On-device checklist confirming the property walkthrough and logged maintenance items.

Voice & Text Observations

Observations below were recorded on-site as voice notes and automatically transcribed, or entered directly as text, through the Preserver app.

Time	Type	Transcript / Note
11:05 AM	Voice	"There's a water stain on the ceiling in the corner here, bit of mould spotting too. Looks like an old leak, not active right now, but worth flagging for maintenance."
11:18 AM	Voice	"Kitchen cabinet hinge is loose, easy fix. Everything else in the kitchen is in good shape."
11:28 AM	Text	Walkthrough checklist completed — ceiling stain and cabinet hinge logged, remaining rooms in good condition.

Site Visit Log

11:00 AM	Activity started on-site — GPS lock confirmed, tenanted property
11:05 AM	Ceiling & walls — photo + voice observation logged
11:18 AM	Kitchen — photo + voice observation logged
11:28 AM	Inspection checklist — photo + text observation logged
11:34 AM	Activity ended and locked — record sealed, tamper-evident

How This Report Was Produced

This report was generated from a single Preserver export — no re-typing, no separate note-taking app, and no manual GPS lookups. During the visit, every photo, voice note and text entry was captured in one place, each automatically stamped with the time and exact location it was recorded.

At the end of the visit, the activity was locked directly in the app, sealing the record so nothing could be altered after the fact. The full activity — photos, transcripts, GPS log and metadata — was then exported in one step (JSON + Photos) and handed to an AI assistant, which produced the structured report above in a matter of minutes.

The result: a defensible, timestamped, location-verified record of the inspection, turned into an owner-ready condition report the same day it was captured.

Preserver

Free to capture. Record your observations — photo, video, voice or text — with GPS and timestamp on every entry. Export anywhere, including straight to AI. preserver.me