

Structural Inspection Report

Client: Demo data - privacy protected · Site structural inspection
Visit Date: 28 September 2026, 7:30 AM – 7:52 AM
Generated by: AI report assistant, from a Preserver field export

Summary

A structural inspection was carried out at an active construction site, covering a foundation crack assessment, a reinforcement steel check ahead of the next concrete pour, and a review of the site's structural checklist. All observations were captured on-site using the Preserver app, with GPS location and timestamp data recorded automatically alongside supporting photos and voice notes converted to text.

Overall, a hairline crack was identified in the foundation slab and measured for monitoring, reinforcement steel placement matched the engineering drawings, and the structural checklist was completed with no items outstanding. The crack has been flagged for re-inspection at the next site visit.

Inspection Summary

Category	Observation	Status	Action Required
Foundation Crack	Hairline crack, 0.3mm width, measured and marked	Monitor	Re-inspect next visit
Reinforcement Steel	Rebar spacing and cover match engineering drawings	Compliant	Clear to pour
Structural Checklist	Site checklist completed, no items outstanding	Compliant	No action

Field Evidence

The following images and captions were captured directly through the Preserver app during the visit. Each entry retains its original GPS coordinates and capture timestamp. Demo data - privacy protected.



Foundation crack — measured hairline crack

-27.4623, 153.0102 · 28 Sep 2026, 7:34 AM

Hairline crack in the foundation slab measured at 0.3mm width and marked for ongoing monitoring.



Reinforcement check — exposed rebar in footing

-27.4624, 153.0103 · 28 Sep 2026, 7:41 AM

Exposed reinforcement steel in the footing checked against the engineering drawings for spacing and cover.



Site checklist — structural inspection sign-off

-27.4623, 153.0101 · 28 Sep 2026, 7:48 AM

On-device structural checklist for the site visit, completed and signed off with no outstanding items.

Voice & Text Observations

Observations below were recorded on-site as voice notes and automatically transcribed, or entered directly as text, through the Preserver app.

Time	Type	Transcript / Note
7:34 AM	Voice	"Found a hairline crack in the foundation slab, measuring about zero-point-three millimetres. Marking it here for monitoring, nothing urgent."
7:41 AM	Voice	"Rebar spacing and cover on this footing line up with the drawings. Good to proceed with the pour."
7:48 AM	Text	Structural checklist completed for this section — no outstanding items, site clear for next phase.

Site Visit Log

7:30 AM	Activity started on-site — GPS lock confirmed, construction site
7:34 AM	Foundation crack check — photo + voice observation logged
7:41 AM	Reinforcement check — photo + voice observation logged
7:48 AM	Structural checklist — photo + text observation logged
7:52 AM	Activity ended and locked — record sealed, tamper-evident

How This Report Was Produced

This report was generated from a single Preserver export — no re-typing, no separate note-taking app, and no manual GPS lookups. During the visit, every photo, voice note and text entry was captured in one place, each automatically stamped with the time and exact location it was recorded.

At the end of the visit, the activity was locked directly in the app, sealing the record so nothing could be altered after the fact. The full activity — photos, transcripts, GPS log and metadata — was then exported in one step (JSON + Photos) and handed to an AI assistant, which produced the structured report above in a matter of minutes.

The result: a defensible, timestamped, location-verified record of the inspection, turned into a site-ready report the same day it was captured.

Preserver

Free to capture. Record your observations — photo, video, voice or text — with GPS and timestamp on every entry. Export anywhere, including straight to AI. preserver.me