

Trade Job Site Report

Client: Demo data - privacy protected · Residential job site visit
Visit Date: 28 September 2026, 8:05 AM – 8:26 AM
Generated by: AI report assistant, from a Preserver field export

Summary

A residential job site visit was carried out to complete a switchboard inspection, install a new light fixture, and stage tools and materials for the next phase of the job. All observations were captured on-site using the Preserver app, with GPS location and timestamp data recorded automatically alongside supporting photos and voice notes converted to text.


Overall, the switchboard tested within normal parameters, the new light fixture was installed and confirmed working, and tools were staged ready for tomorrow's follow-up. No safety issues were identified, and the job remains on schedule for handover by the end of the week.

Job Summary

Category	Observation	Status	Action Required
Switchboard Test	Multimeter reading within normal range, no faults found	Compliant	No action
Fixture Installation	New light fixture installed and tested, working correctly	Complete	No action
Tools & Materials	Tools and materials staged for next visit	On Track	Continue tomorrow

Field Evidence

The following images and captions were captured directly through the Preserver app during the visit. Each entry retains its original GPS coordinates and capture timestamp. Demo data - privacy protected.



Switchboard test — multimeter reading

-27.4560, 152.9877 · 28 Sep 2026, 8:09 AM

Multimeter reading taken across the switchboard circuits, confirming voltage within normal operating range.



Tools staged — job site toolbox and ladder

-27.4561, 152.9878 · 28 Sep 2026, 8:16 AM

Tools and materials laid out and staged ahead of tomorrow's follow-up work on site.



Fixture installed — new light fixture check

-27.4560, 152.9876 · 28 Sep 2026, 8:22 AM

Newly installed light fixture photographed and tested, confirming correct operation.

Voice & Text Observations

Observations below were recorded on-site as voice notes and automatically transcribed, or entered directly as text, through the Preserver app.

Time	Type	Transcript / Note
8:09 AM	Voice	"Switchboard's testing fine, readings are all within normal range. No faults on this circuit."
8:16 AM	Voice	"Got the tools and materials staged for tomorrow, should be able to knock the rest of this out first thing."
8:22 AM	Text	New light fixture installed and tested — working correctly, no flicker or wiring issues.

Site Visit Log

8:05 AM	Activity started on-site — GPS lock confirmed, residential address
8:09 AM	Switchboard test — photo + voice observation logged
8:16 AM	Tools staged — photo + voice observation logged
8:22 AM	Fixture installation — photo + text observation logged
8:26 AM	Activity ended and locked — record sealed, tamper-evident

How This Report Was Produced

This report was generated from a single Preserver export — no re-typing, no separate note-taking app, and no manual GPS lookups. During the visit, every photo, voice note and text entry was captured in one place, each automatically stamped with the time and exact location it was recorded.

At the end of the visit, the activity was locked directly in the app, sealing the record so nothing could be altered after the fact. The full activity — photos, transcripts, GPS log and metadata — was then exported in one step (JSON + Photos) and handed to an AI assistant, which produced the structured report above in a matter of minutes.

The result: a defensible, timestamped, location-verified record of the job, turned into a client-ready report the same day it was captured.

Preserver

Free to capture. Record your observations — photo, video, voice or text — with GPS and timestamp on every entry. Export anywhere, including straight to AI. preserver.me