

Mine Site Inspection Report

Client: Demo data - privacy protected · Open-cut site inspection
Visit Date: 28 September 2026, 6:45 AM – 7:50 AM
Generated by: AI report assistant, from a Preserver field export

Summary

A routine site inspection was carried out at the open-cut mine, covering the general pit and haul road condition, a berm edge erosion check, and pre-shift equipment and PPE sign-off. All observations were captured on-site using the Preserver app, with GPS location and timestamp data recorded automatically alongside supporting photos and voice notes converted to text.

The pit and haul roads were in good general condition, a small erosion crack was identified on one haul road berm edge and flagged for maintenance, and pre-shift checklist and PPE items were confirmed complete before work began.

Inspection Summary

Category	Observation	Status	Action Required
Pit & Haul Roads	General condition good, no major hazards	On Track	None
Haul Road Berm	Small erosion crack on one berm edge	Attention	Schedule maintenance
Pre-Shift Checklist	PPE and equipment checklist signed off	Complete	None

Field Evidence

The following images and captions were captured directly through the Preserver app during the visit. Each entry retains its original GPS coordinates and capture timestamp. Demo data - privacy protected.



Open-cut pit — general condition

-22.4567, 148.1234 · 28 Sep 2026, 6:50 AM

Wide view of the open-cut pit and haul roads, general condition checked at shift start.



Haul road berm — erosion check

-22.4570, 148.1238 · 28 Sep 2026, 7:15 AM

Small erosion crack identified on the haul road berm edge, flagged for maintenance.



Pre-shift — checklist and PPE sign-off

-22.4565, 148.1230 · 28 Sep 2026, 7:40 AM

Pre-shift equipment checklist and PPE confirmed complete before work began.

Voice & Text Observations

Observations below were recorded on-site as voice notes and automatically transcribed, or entered directly as text, through the Preserver app.

Time	Type	Transcript / Note
6:50 AM	Voice	"Pit and haul roads are looking good this morning, nothing major to flag on the general walk."
7:15 AM	Voice	"There's a small erosion crack on the berm edge along the main haul road — worth getting maintenance out to it."
7:40 AM	Text	Pre-shift checklist and PPE confirmed complete before start of work.

Site Visit Log

6:45 AM	Activity started on-site — GPS lock confirmed, mine site location
6:50 AM	Pit and haul road check — photo + voice observation logged
7:15 AM	Berm edge inspection — photo + voice observation logged
7:40 AM	Pre-shift sign-off — photo + text observation logged
7:50 AM	Activity ended and locked — record sealed, tamper-evident

How This Report Was Produced

This report was generated from a single Preserver export — no re-typing, no separate note-taking app, and no manual GPS lookups. During the visit, every photo, voice note and text entry was captured in one place, each automatically stamped with the time and exact location it was recorded.

At the end of the visit, the activity was locked directly in the app, sealing the record so nothing could be altered after the fact. The full activity — photos, transcripts, GPS log and metadata — was then exported in one step (JSON + Photos) and handed to an AI assistant, which produced the structured report above in a matter of minutes.

The result: a defensible, timestamped, location-verified record of the inspection, turned into a supervisor-ready report the same day it was captured.

Preserver

Free to capture. Record your observations — photo, video, voice or text — with GPS and timestamp on every entry. Export anywhere, including straight to AI. preserver.me