

Water Infrastructure Inspection Report

Client: Demo data - privacy protected · Reservoir and network inspection

Visit Date: 28 September 2026, 7:15 AM – 8:30 AM

Generated by: AI report assistant, from a Preserver field export

Summary

A water infrastructure inspection was carried out across the reservoir and local distribution network, covering a reservoir valve and pipework check, a digital meter and pressure reading, and a pipe repair site inspection. All observations were captured on-site using the Preserver app, with GPS location and timestamp data recorded automatically alongside supporting photos and voice notes converted to text.

The reservoir valve and pipework were confirmed in good operating condition, meter and pressure readings were within normal range, and the pipe repair excavation was inspected and found complete and ready for backfill.

Inspection Summary

Category	Observation	Status	Action Required
Reservoir & Valves	Valve and pipework in good operating condition	On Track	None
Meter & Pressure	Digital meter and pressure readings within normal range	Complete	None
Pipe Repair Site	Excavation complete, ready for backfill	On Track	Schedule backfill crew

Field Evidence

The following images and captions were captured directly through the Preserver app during the visit. Each entry retains its original GPS coordinates and capture timestamp. Demo data - privacy protected.



Reservoir — valve and pipework check
-27.4512, 153.0234 · 28 Sep 2026, 7:20 AM

Reservoir storage valve and pipework inspected, confirmed in good operating condition.



Distribution network — meter and pressure reading
-27.4518, 153.0241 · 28 Sep 2026, 7:52 AM

Digital water meter and pressure gauge checked at the network access point, readings within normal range.



Pipe repair — excavation inspection
-27.4523, 153.0248 · 28 Sep 2026, 8:18 AM

Water pipe repair excavation inspected, section exposed and confirmed complete ahead of backfill.

Voice & Text Observations

Observations below were recorded on-site as voice notes and automatically transcribed, or entered directly as text, through the Preserver app.

Time	Type	Transcript / Note
7:20 AM	Voice	"Reservoir valve's looking good this morning, pipework's holding pressure fine, nothing to flag."
7:52 AM	Voice	"Meter and pressure readings are both sitting within normal range at this access point."
8:18 AM	Text	Pipe repair excavation inspected, section exposed and ready for backfill crew.

Site Visit Log

7:15 AM	Activity started on-site — GPS lock confirmed, reservoir location
7:20 AM	Reservoir valve check — photo + voice observation logged
7:52 AM	Meter and pressure reading — photo + voice observation logged
8:18 AM	Pipe repair inspection — photo + text observation logged
8:30 AM	Activity ended and locked — record sealed, tamper-evident

How This Report Was Produced

This report was generated from a single Preserver export — no re-typing, no separate note-taking app, and no manual GPS lookups. During the visit, every photo, voice note and text entry was captured in one place, each automatically stamped with the time and exact location it was recorded.

At the end of the visit, the activity was locked directly in the app, sealing the record so nothing could be altered after the fact. The full activity — photos, transcripts, GPS log and metadata — was then exported in one step (JSON + Photos) and handed to an AI assistant, which produced the structured report above in a matter of minutes.

The result: a defensible, timestamped, location-verified record of the inspection, turned into a supervisor-ready report the same day it was captured.

Preserver

Free to capture. Record your observations — photo, video, voice or text — with GPS and timestamp on every entry. Export anywhere, including straight to AI. preserver.me