

RESIDENTIAL PROPERTY INSPECTION REPORT

Seattle Modern
1847 15th Ave E, Seattle, WA

ELECTRICAL SYSTEM

Electrical panel meets all safety standards. Breakers function properly with no signs of overheating or corrosion.




Photo: ELECTRICAL SYSTEM

SUMMARY

Overall property condition is acceptable. Recommend standard monitoring and maintenance.