

RESIDENTIAL PROPERTY INSPECTION REPORT

Minneapolis New Build
7890 Lyndale Ave, Minneapolis, MN

FOUNDATION & STRUCTURAL

Foundation is in excellent condition with smooth concrete surfaces. No cracks, settlement, or structural concerns observed. Properly installed and well-maintained.



Photo: FOUNDATION & STRUCTURAL

SUMMARY

Property exceeds expectations. All systems in excellent working order. Highly recommended.