

# RESIDENTIAL PROPERTY INSPECTION REPORT

**Chicago Bungalow**  
**2847 N Kedzie Ave, Chicago, IL**

## FOUNDATION & STRUCTURAL

Foundation walls appear structurally sound with no visible signs of settlement or movement. No remediation recommended.



*Photo: FOUNDATION & STRUCTURAL*

## SUMMARY

Overall property condition is acceptable. Recommend standard monitoring and maintenance.