

RESIDENTIAL PROPERTY INSPECTION REPORT

Austin Condo
1520 S Congress, Austin, TX

BATHROOM SYSTEMS

Tile installation shows quality workmanship. Grout lines are clean with no evidence of moisture penetration.




Photo: BATHROOM SYSTEMS

SUMMARY

Overall property condition is acceptable. Recommend standard monitoring and maintenance.