

RESIDENTIAL PROPERTY INSPECTION REPORT

Nashville New Build
4567 West End Ave, Nashville, TN

ROOF SYSTEM

Roof is in excellent condition with all shingles intact and properly installed. Professional workmanship evident throughout.



Photo: ROOF SYSTEM

SUMMARY

Property exceeds expectations. All systems in excellent working order. Highly recommended.