

RESIDENTIAL PROPERTY INSPECTION REPORT

San Diego New Build
4567 La Jolla Blvd, San Diego, CA

BATHROOM SYSTEMS

Bathroom tile installation is in perfect condition. Grout lines are clean and properly sealed with no mold or mildew present.



Photo: BATHROOM SYSTEMS

SUMMARY

Property exceeds expectations. All systems in excellent working order. Highly recommended.