

RESIDENTIAL PROPERTY INSPECTION REPORT

San Francisco Victorian
2134 Haight St, San Francisco, CA

ELECTRICAL SYSTEM

Electrical panel meets all safety standards. Breakers function properly with no signs of overheating or corrosion.




Photo: ELECTRICAL SYSTEM

SUMMARY

Overall property condition is acceptable. Recommend standard monitoring and maintenance.