

# RESIDENTIAL PROPERTY INSPECTION REPORT

**Las Vegas Home**  
**4567 Paradise Rd, Las Vegas, NV**

## PLUMBING SYSTEM

Plumbing in excellent condition. No signs of corrosion or leaking at visible connections.



*Photo: PLUMBING SYSTEM*

## SUMMARY

Overall property condition is acceptable. Recommend standard monitoring and maintenance.