

# RESIDENTIAL PROPERTY INSPECTION REPORT

**Chicago Renovation**  
**4567 N Clark St, Chicago, IL**

## FOUNDATION & STRUCTURAL

Foundation is in excellent condition with smooth concrete surfaces. No cracks, settlement, or structural concerns observed. Properly installed and well-maintained.



*Photo: FOUNDATION & STRUCTURAL*

## SUMMARY

Property exceeds expectations. All systems in excellent working order. Highly recommended.