

RESIDENTIAL PROPERTY INSPECTION REPORT

Austin Modern Home
3456 S Lamar Blvd, Austin, TX

ELECTRICAL SYSTEM

Electrical panel shows pristine condition with clean copper bus bars. All connections are properly installed with no rust or corrosion observed.




Photo: ELECTRICAL SYSTEM

SUMMARY

Property exceeds expectations. All systems in excellent working order. Highly recommended.