

RESIDENTIAL PROPERTY INSPECTION REPORT

San Francisco Condo
567 Market St, San Francisco, CA

ELECTRICAL SYSTEM

Electrical panel shows pristine condition with clean copper bus bars. All connections are properly installed with no rust or corrosion observed.




Photo: ELECTRICAL SYSTEM

SUMMARY

Property exceeds expectations. All systems in excellent working order. Highly recommended.