

RESIDENTIAL PROPERTY INSPECTION REPORT

Miami Condo

1100 Biscayne Blvd, Miami, FL

ELECTRICAL SYSTEM

Electrical panel meets all safety standards. Breakers function properly with no signs of overheating or corrosion.




Photo: ELECTRICAL SYSTEM

SUMMARY

Overall property condition is acceptable. Recommend standard monitoring and maintenance.