

RESIDENTIAL PROPERTY INSPECTION REPORT

Atlanta Home
789 Peachtree St NE, Atlanta, GA

BATHROOM SYSTEMS

Tile installation shows quality workmanship. Grout lines are clean with no evidence of moisture penetration.



Photo: BATHROOM SYSTEMS

SUMMARY

Overall property condition is acceptable. Recommend standard monitoring and maintenance.