

RESIDENTIAL PROPERTY INSPECTION REPORT

New Orleans House
1234 Magazine St, New Orleans, LA

BATHROOM SYSTEMS

Tile installation shows quality workmanship. Grout lines are clean with no evidence of moisture penetration.



Photo: BATHROOM SYSTEMS

SUMMARY

Overall property condition is acceptable. Recommend standard monitoring and maintenance.