

RESIDENTIAL PROPERTY INSPECTION REPORT

Seattle New Home

1234 Queen Anne Ave, Seattle, WA

ELECTRICAL SYSTEM

Electrical panel shows pristine condition with clean copper bus bars. All connections are properly installed with no rust or corrosion observed.




Photo: ELECTRICAL SYSTEM

SUMMARY

Property exceeds expectations. All systems in excellent working order. Highly recommended.