

RESIDENTIAL PROPERTY INSPECTION REPORT

Charlotte Home
1234 Queens Rd, Charlotte, NC

PLUMBING SYSTEM

Plumbing system is in pristine condition. All connections are professionally installed with no signs of leaking or corrosion.



Photo: PLUMBING SYSTEM

SUMMARY

Property exceeds expectations. All systems in excellent working order. Highly recommended.