

Work Order WO-141 — Mechanical seal replaced

Plant: Shakti Petrochem Unit-2 | **Asset:** P-204A | **Date:** 2026-06-18 | **Status:** closed

Description

Planned replacement of cartridge mechanical seal on P-204A following WO-129.

Findings

Seal cartridge replaced. Coupling guard refitted.

Action Taken

Seal replaced. NOTE: post-repair vibration reading NOT recorded; alignment check not documented.

Post-Repair Test

MISSING