Coolfix Home Services (demo)

Service job card. Air conditioners. Pune.

Job no.	Date
CF-9201	26 May 2026

Customer	Area
V. Pillai	Hadapsar

Unit model	Serial no.
Coolwave CS-157	MS2-68977

Complaint

Water dripping indoor

Suction (psi)	Compressor (A)	Supply air (C)
110	5.8	9

Work done

Drain cleared. Filters dusty, cleaned

Parts used

None

Remarks

Construction work next door, lot of dust

Next service	Technician
Nov 2026	Anil

☑ Filters cleaned ☐ Gas topped up ☑ Customer informed

Customer signature

Pillai