

MAINTENANCE & REPAIR REPORT

Plant Engineering Dept. · Form ME-07 Rev C

REPORT NO.

RPT-4009

FAULT PATTERN ID

FP-02

DATE OF FAILURE

25/01/2024 06:00

ASSET ID

AST-011

MODEL NO.

DAIKIN-JT160

LINKED WO

-

SYMPTOMS OBSERVED

Head pressure high, temp trending up 10 days. Cond filter overdue.

DIAGNOSIS / ROOT CAUSE

Filter overdue - PM missed during shutdown

PARTS REPLACED

FLT-COND-JT160

DOWNTIME (HRS)

2.5

FAULT CATEGORY

Cooling Degradation

TECHNICIAN

S. Kadam

SIGNATURE

