

MAINTENANCE & REPAIR REPORT

Plant Engineering Dept. · Form ME-07 Rev C

REPORT NO.

RPT-4020

FAULT PATTERN ID

FP-04

DATE OF FAILURE

09/01/2026 12:00

ASSET ID

AST-004

MODEL NO.

SIEM-1LE1

LINKED WO

-

SYMPTOMS OBSERVED

Speed oscillation with 8s period under full load. Tension ok, sheave key worn.

DIAGNOSIS / ROOT CAUSE

Sheave key wear - backlash hunting

PARTS REPLACED

nil

DOWNTIME (HRS)

5.0

FAULT CATEGORY

Belt Slip Rpm

TECHNICIAN

S. Kadam

SIGNATURE

