# NATIONAL BUILDING RESEARCH ORGANISATION

## STRUCTURAL ENGINEERING RESEARCH & PROJECT MANAGEMENT DIVISION

## ANNEX - I | DEFECT NOTATION REFERENCE

| Photo table type | Defect type | Notation | Description | Remarks |
|---|---|---|---|---|
| Type 01 - Building floor | Cracks | C, BC, CC, FC, SC, TC | Wall, beam, column, floor, slab or tile crack | Use the appropriate element notation. |
| — | Separations | SP | Separation | Specify wall-wall, beam-wall, column-wall, floor-wall or slab-beam in remarks. |
| — | Damages | D, WD, BD, CD, FD, SD, TD, GD, PD, RD | Damaged area; wall, beam, column, floor, slab, tile, glass, plaster or roof damage | Sun shed, ceiling and door/window frame damage may be noted under D. |
| — | Patches | DP | Damp patch | Specify whether on wall, slab, beam or column. |
| Type 02 - Boundary wall | Cracks | BWC | Boundary wall crack | — |
| — | Separations | BWSP | Boundary wall separation | — |
| — | Damages | BWD | Boundary wall damage | — |
| — | Patches | BWDP | Damp patch on boundary wall | — |

# BUIDLING INSPECTION REPORT

## PRE-CRACK SURVEY REPORT ON BUILDINGS AROUND PREMISES

### no.285/275,main road kandy

### FOR NATIONAL BUILDING RESEARCH ORGANISATION

| | |
|---|---|
| **Building Reference No.** | H-002 |
| **Name of Owner** | Mr.Nimal Perera |
| **Report ID** | 0d65fdf7-548f-44f9-b588-a91634caf1cd |



**Front view of the building** **Situation as at 03.10.2026**

# PRE-CRACK SURVEY REPORT ON BUILDINGS AROUND PREMISES

## SITE DATA SHEET

| | | | |
|---|---|---|---|
| **Name of Owner** | Mr.Nimal Perera | **Building Ref. No.** | H-002 |
| **Address of Premises** | no.285/275,main road kandy | **Contact No.** | 0742356135 |
| **GPS Coordinates** | N: 6.0640009<br>E: 80.719953 | **Distance from Row** | 19.0 m |

## 1. General Observations

| No. | Type | Present Condition | Approx. Age |
|---|---|---|---|
| 1 | House | Semi-permanent / Temporary | 19 |

## 2. External Services

| No. | Pipe-borne Water Supply | Sewage / Waste Water | Electricity |
|---|---|---|---|
| 1 | From main supply | Connected to Sewer Main | From Private Solar supply |

## 3. Details of Ancillary Buildings / Structures

| No. | Details | Front | Left | Right | Rear |
|---|---|---|---|---|---|
| *No ancillary building records are available.* | | | | | |

## 4. Details of Main Building Elements

| No. | Building ID | Number of Floors | Sync Status |
|---|---|---|---|
| 1 | 8e3def98-da1e-4739-8502-3dc8d9f68414 | G+1 | — |

## Main Building Specifications

| Element | In Use | Element Properties | Floor Details |
|---|---|---|---|
| wall\|Brick (9" thick wall) | Yes | — | — |
| wall\|Brick (4.5" thick wall) | Yes | — | — |
| door\|Solid Timber | Yes | — | — |
| door\|Other Timber | Yes | — | — |
| door\|Glazed Aluminium | Yes | — | — |
| floor\|Timber | Yes | — | — |
| floor\|Cement Rendered Floor | Yes | — | — |
| floor\|Floor Tiles | Yes | — | — |
| roof\|Single Pitched | Yes | — | — |
| roof\|Gable | Yes | — | — |
| roof\|Hipped | Yes | — | — |
| roofcovering\|Clay Tiles | Yes | — | — |

## 5. Details / Photographs of Defects

Defect records for the selected premises

| Defect No. | Length (mm) | Width (mm) | Photograph/s of Defect | Description / Remarks |
|---|---|---|---|---|
| D | 13 | 295 |  | boundaryWall<br>1st<br>hiii<br>hiii |