NATIONAL BUILDING RESEARCH ORGANISATION

STRUCTURAL ENGINEERING RESEARCH & PROJECT MANAGEMENT DIVISION

ANNEX - I | DEFECT NOTATION REFERENCE

Photo table type	Defect type	Notation	Description	Remarks
Type 01 - Building floor	Cracks	C, BC, CC, FC, SC, TC	Wall, beam, column, floor, slab or tile crack	Use the appropriate element notation.
—	Separations	SP	Separation	Specify wall-wall, beam-wall, column-wall, floor-wall or slab-beam in remarks.
—	Damages	D, WD, BD, CD, FD, SD, TD, GD, PD, RD	Damaged area; wall, beam, column, floor, slab, tile, glass, plaster or roof damage	Sun shed, ceiling and door/window frame damage may be noted under D.
—	Patches	DP	Damp patch	Specify whether on wall, slab, beam or column.
Type 02 - Boundary wall	Cracks	BWC	Boundary wall crack	—
—	Separations	BWSP	Boundary wall separation	—
—	Damages	BWD	Boundary wall damage	—
—	Patches	BWDP	Damp patch on boundary wall	—

BUIDLING INSPECTION REPORT

PRE-CRACK SURVEY REPORT ON BUILDINGS AROUND PREMISES

no.123/2

FOR NATIONAL BUILDING RESEARCH ORGANISATION

Building Reference No.	H-001
Name of Owner	mr.test1
Report ID	9e91873d-1adf-4ba3-a57f-d7f46db45204



Front view of the building **Situation as at 03.10.2026**

PRE-CRACK SURVEY REPORT ON BUILDINGS AROUND PREMISES

SITE DATA SHEET

Name of Owner	mr.test1	**Building Ref. No.**	H-001
Address of Premises	no.123/2	**Contact No.**	071243526
GPS Coordinates	N: 6.0640009 E: 80.719953	**Distance from Row**	19.0 m

1. General Observations

No.	Type	Present Condition	Approx. Age
1	House	Permanent	19

2. External Services

No.	Pipe-borne Water Supply	Sewage / Waste Water	Electricity
1	From Well	Connected to Sewer Main	From Main supply

3. Details of Ancillary Buildings / Structures

No.	Details	Front	Left	Right	Rear
No ancillary building records are available.					

4. Details of Main Building Elements

No.	Building ID	Number of Floors	Sync Status
1	e913d5ab-77c4-4534-bda3-98ee72c07774	G+1	—

Main Building Specifications

Element	In Use	Element Properties	Floor Details
wall|Brick (9" thick wall)	Yes	—	—
wall|Cement Block work	Yes	—	—
wall|Other	Yes	—	—
door|Solid Timber	Yes	—	—
door|Other Timber	Yes	—	—
door|Glazed Aluminium	Yes	—	—
floor|Brick Paved	Yes	—	—
floor|Cement Rendered Floor	Yes	—	—
floor|Smooth Plastered	Yes	—	—
roof|Single Pitched	Yes	—	—
roof|Hipped	Yes	—	—
roofcovering|Asbestos	Yes	—	—

5. Details / Photographs of Defects

Defect records for the selected premises

Defect No.	Length (mm)	Width (mm)	Photograph/s of Defect	Description / Remarks
BD	1235	46533		boundaryWall 1st hi hi