



Machine Name:

Fabric Color:

Material Type:


Date: 2023-12-07

Time :6AM to 6PM

Fabric Inspection Report

Shiftwise Roll Id	Start Time	End Time	Time Taken	No of Revolutions	Lycra	Needle line	Hole	Other	Decision
1	23:20	13:52	14h 32m	3300	1	0	0	twoply: 1 shutoff: 1	
2	13:52	14:08	0h 16m	244	0	0	0	0	
3	14:08	18:24	4h 16m	3300	1	0	0	0	
4	18:24	running	running	3300	0	0	0	0	

Production Report & Defect Report



Defect Log Report

Time	Defect Type	Revolution	Rollno	Shift
00:41:03	twoply	1082	1	Shift C
11:29:16	lycra	1361	1	Shift A
13:35:16	shutoff	3067	1	Shift A
15:25:05	lycra	945	3	Shift B