



No : 32289903

DATE: 2020-06-17T21:00:00.000Z

LOCATION : **KEEMK**

INWARD EQUIPMENT INTERCHANGE

CONTAINER NO: MAGU2523324

22G0

SEAL -

DEST KEMBA

SHIPPING LINE : CMA CGM KENYA LTD

VESSEL : EMIRATES ASANTE

TRANSPORTER: MURANGA

DRIVER : HESBON KEN


PARTY DELIVERING CONTAINER: MURANGA

B\L NO: 32289903

VOY NO:ESA/0740/2020

TRUCK NO: KCW001H

DELIVERY NOTE:



Tally Report

MINOR DENTS AND SCRATCHES SEEN

Repair Code Description of Damage/Repair Qty Hours Labour Cost\$ Material Cost Total Cost

BSRF ST/1 Straighten Bottom Side Rail Flange upto first 15 cm 0.15 96

96

Prepared by : Kennedy Walucho Repair Estima

Repair Estimated by: Kennedy Walucho

Distribution: 1, Transporter: 2, Shpg Line 3 BBL