



No: 82470588

DATE: 2020-06-01

LOCATION : **KEEMK**

INWARD EQUIPMENT INTERCHANGE

CONTAINER NO: MAGU2523324

22G0

SEAL -

DEST KEMBA

SHIPPING LINE : CMA CGM KENYA LTD

VESSEL: EMIRATES ASANTE

TRANSPORTER: MURANGA

DRIVER : Luis Nani


PARTY DELIVERING CONTAINER: MURANGA

B\L NO: 82470588

VOY NO:ESA/0740/2020

TRUCK NO: KOR 233U

DELIVERY NOTE:



Tally Report

MINOR DENTS AND SCRATCHES SEEN

Repair Code Description of Damage/Repair Qty Hours Labour Cost\$ Material Cost Total Cost

BSRF ST/2 Straighten Bottom Side Rail Flange 30 cm 0.25 195

195

Prepared by: AUGUSTINE AUGUSTINE

Repair Estimated by: AUGUSTINE AUGUSTINE

Distribution: 1, Transporter: 2, Shpg Line 3 BBL