

No :

DATE : 2020-06-17

LOCATION : KEEMK

INWARD EQUIPMENT INTERCHANGE

CONTAINER NO :SEGU4887422

45G0

SEAL -

DEST KEMBA

SHIPPING LINE : CMA CGM KENYA LTD

B\L NO :

VESSEL : BERMUDA

VOY NO:BRMD/0610/2020

TRANSPORTER : IRIS SOLUTIONS

TRUCK NO: KBS 002P

DRIVER : WANYONYI

DELIVERY NOTE :

PARTY DELIVERING CONTAINER : IRIS SOLUTIONS



Tally Report

MINOR DENTS AND SCRATCHES SEEN

Repair Code	Description of Damage/Repair Qty	Hours	Labour Cost\$	Material Cost	Total Cost
					0

Prepared by : AUGUSTINE AUGUSTINE

Repair Estimated by: AUGUSTINE AUGUSTINE

Distribution : 1, Transporter : 2, Shpg Line 3 BBL