

No :

DATE : 2020-06-16T21:00:00.000Z

LOCATION : KEEMK

INWARD EQUIPMENT INTERCHANGE

CONTAINER NO : CMAU7660486

45G0

SEAL -

DEST KEMBA

SHIPPING LINE : CMA CGM KENYA LTD

B\L NO :

VESSEL : null

VOY NO: BLWL/0609/2020


TRANSPORTER : CMAU7660486

TRUCK NO: KCB 123L

DRIVER : KEN WALIBORA

DELIVERY NOTE :

PARTY DELIVERING CONTAINER : CMAU7660486



Tally Report

MINOR DENTS AND SCRATCHES SEEN

Repair Code	Description of Damage/Repair Qty	Hours	Labour Cost\$	Material Cost	Total Cost
					0

Prepared by : AUGUSTINE AUGUSTINE

Repair Estimated by: AUGUSTINE AUGUSTINE

Distribution : 1, Transporter : 2, Shpg Line 3 BBL