

No : 646

DATE : 05/12/2019

LOCATION : SNT

INWARD EQUIPMENT INTERCHANGE

CONTAINER NO : 00CU70264 40 FT GP

SEAL -

 DEST
KEMBA

SHIPPING LINE : SNT

BL NO : 00CU70264

VESSEL : SIGINON TERMINAL

NO:

TRANSPORTER : SANALSA LTD

TRUCK NO : KBR 370

DRIVER : BOAS/ 28295848


DELIVERY NOTE :

PARTY DELIVERING CONTAINER : SANALSA LTD

STORAGE :

CNTR IN DATE : 05/12/2019

STATUS : LCL



EMPTY CONTAINER

00CU7020674

Tally Report

MINOR DENTS AND SCRATCHES SEEN

Repair Code	Description of Damage/Repair	Qty	Hours	Labour	Cost\$	Material Cost	Total Cost
-------------	------------------------------	-----	-------	--------	--------	---------------	------------

Prepared by : Amos

SIGINON CFS

Repair Estimated by

Date

Delivering driver signature

Date

Distribution : 1, Transporter : 2, Shpg Line 3 SIG