

# MUTNEJA Tech

Insurance Surveyors and Loss Assessors Pvt. Ltd.

Mobile : 9910995122(DLH NCR),9468881222(GURUGRAM),9414088243,6378710966,7597233966(RAJASTHAN)

Email: Info@mutnejatech.co.in

Lic No. IRDA/CORP/SLA-200018 DOE 07.02.2025

Ref No. : MSL/DLH/2024/11/10027A

Date : 11-Dec-23

## MOTOR SPOT SURVEY REPORT

This report is issued by me/us as a licensed Surveyor(s) without prejudice in respect of cause, nature and extent of loss/damages and subject to the terms and conditions of the insurance policy.

Policy / Cover Note No. : 2230003123P101941626 IDV : ₹ 3,644,157.00  
Period of Insurance : 31-May-23 to 30-May-24 Claim No. : -

1. **Insurers** : United India Insurance Co. Ltd.  
223000- Divisional Office-30 (Gurugram) Unit No. 34, 35, 6A, GB, Ground Floor, Vipul Trade Centre,  
Sector-48, Sohna Road, Gurugram

Appointed By 223000- Divisional Office-30 (Gurugram)

2. **Insured** : M/s Saisha Infra Projects Ltd.,  
817-A, Block-B, Sushant City, Panipat, Haryana 132103

3. **H. P. A.** : HDFC Bank Ltd., Gurgaon

4. **VEHICLE PARTICULARS :** Original To Be Check  
(a) Registered Number : HR55AL4792  
(b) Registered Owner : M/s Saisha Infra Projects Ltd.  
Owner Serial No. / Transfer date : 01  
(c) Date of Registration : 08-Jun-22  
(d) Chassis Number : MEC841FBANP115256 ( Physically Checked )  
(e) Engine Number : 926956D0119617  
(f) Make / Variant/ Model : Daimler India Commercial Vehic/Bharat Benz 2828C 6X4 Bsvin3g 4/2022  
(g) Type of Body : Tipper Body  
(h) Class of Vehicle : Goods Carrier- TR  
(i) Pre Accident Condition : Average  
(j) Registered Laden Weight : 28000 Kgs.  
(k) UnLaden Weight : 11590 Kgs.  
(l) Seating Capacity : 03  
(m) Cubic Capacity : 7200 CC Fuel Used : Diesel  
(n) Tax particulars : To Be Check  
(o) Colour of Vehicle : Yellow  
(p) Fitness Certificate Number : As Per Rc  
Valid Upto : 07/06/2024  
(q) Permit Number : To Be Check  
Valid Upto :  
(r) Type of Permit : To Be Check  
(s) Authorization / validity : To Be Check  
(t) Route/Area of Opration : To Be Check

5. **DRIVER PARTICULARS :** Original To Be Check  
(a) Name of Driver : Gulab Singh S/o Nathu Singh  
Age : 59 Years ( 23-Oct-64 )  
(b) Motor Driver License Number : NL01 19870036257

Date of Issue : 23/01/1987 Valid upto (NTV) : 02/12/2026  
 Valid Form : Valid upto (TV) : 02-Dec-26  
 (c) Issuing Authority : DTO Khetri  
 (d) Type of License : MCWG, LMV, TRANS  
 (e) Badge Number : -

**6. DETAILS OF LOAD CHALLAN / TRIP SHEET DETAILS :**

(a) Nature of Goods Carried and Packing : At the time of accident vehicle was empty.  
 (b) Weight of Goods Carried : Empty  
 (c) Origin - Destination : N.A.  
 (d) L/R Invoice No. & Date : N.A.  
 (e) Transport's Name : N.A.

**7. ACCIDENT PARTICULARS :**

(a) Date & Time of Accident : 20/11/2023 08:22 PM  
 (b) Place of Accident / Survey : Unicorn Enterprises Ram Kunwarpura, Rajasthan  
 (c) Survey Allotment Date : 22-Nov-23  
 (d) Survey Conducted on : 23-Nov-23

**8. CAUSE OF ACCIDENT AS STATED BY INSURED REPRESENTATIVE :**

As filled in the claim form and discussion with the Insured that on the day and time of accident **Gulab Singh S/o Nathu Singh** was driving the subject vehicle. Near spot of accident "The other vehicle was reversing and collided with our vehicle and accident happen causing damages.

**9. FATALITY / INJURIES DETAILS :**

(a) Details of TP Vehicle : No, As stated by the insured.  
 (b) Death/Injury Details of Insured Vehicle : No, As stated by the insured.  
 (c) No of Passangers of Insured Vehicle : 01  
 (d) Death/Injury Details of TP : No, As stated by the insured.  
 (e) Third Party Property Damages : No, As stated by the insured.  
 (f) Person available on spot : Driver  
 (g) Vehicle Will be Shifted to : Workshop/Garage

**10. POLICE ACTION :**

(a) The accident has been reported to the police : No, As stated by the insured  
 (b) Name of Police Station : N.A.  
 (c) FIR No. And Date & Section : N.A.

**11. REMARKS :**

In accordance with the instructions received from **United India Insurance Co. Ltd. 223000- Divisional Office-30 (Gurugram)** dated **22-11-2023** I visited **SPOT** and inspected the subject vehicle, reported to have met with an accident on **20-11-2023** Unicorn Enterprises Ram Kunwarpura, Rajasthan and snapped the vehicle from different angles.

**Observation** : Subject Vehicle with good condition overall. No other damages except as mentioned above were observed over vehicle. Police report of accident not carried out by Insured.

**PARTICULARS OF VISIBLE DAMAGES :**

S. No	Heading	Description
1	FRONT END STRUCTURE / DRIVERS CABIN	Fr Bumper was damaged, Fr Jaali was damaged, Fr W/s glass was broken & Glass Frame also found misaligned, Fr Cowl was damaged.
2	INSTRUMENTS	Looking safe from outward but properly check in the workshop.
3	COOLING SYSTEM	Looking safe from outward but properly check in the workshop.

4	ENGINE & TRANSMISSION	Looking safe.
5	CHASSIS ASSEMBLY	Looking safe from outward but properly check in the workshop.
6	ELECTRICALS	Looking safe from outward but properly check in the workshop.
7	LOAD BODY	Looking safe.
8	FUEL SYSTEM	Looking safe.
9	EXHAUST SYSTEM	Looking safe.
10	BRAKE SYSTEM	Looking safe from outward but properly check in the workshop.
11	STEERING SYSTEM	Looking safe from outward but properly check in the workshop.
12	FRONT SUSPENSION	Looking safe from outward but properly check in the workshop.
13	REAR SUSPENSION	Looking safe.
14	GEAR SYSTEM	Looking safe.
15	WHEEL DISCS & TYRES	Looking safe.

## Notes :

Every care been taken in noting the damages,however if damages found any at the time of final survey can be considered if concurrent with cause of accident.

Thanking you and assuring you of my best services at all times,

**For Mutneja Tech**

Insurance Surveyors & Loss assessors Pvt. Ltd.

Enclosures :