

VAPLI Inspection Telemetry Report

Client: muthu stores | Date: 2026-06-26 | Generated: 27/06/2026 13:06

Professional Inspection Summary

Metric	Value / Count
Total Configured Assets	11
Assets with Readings	1
Assets Pending Readings	10
Compliance Rate	9.1%
Active Unresolved Alerts	5

Assets Pending Inspections (No Readings Today)

- PM3 Flexo Hydraulic (PM3FH)
 - PM3/PM6 Pope Reel Hydraulics (PM3PRH)
 - PM6 M704 (PM6GBM704)
 - muthu (m1)
- PM3 Flexo Lube (PM3FL)
 - PM6 Flexo Lube (PM6FH)
 - PM6 Main Lube (PM6FH)
- PM3 Main Lube (PM3ML)
 - PM6 Kirma Hydraulic (PM6KH)
 - PM6 Unirun (PM6U)

PM6 OILTANKS — Normal Assets

Date Time	Asset Name	Oil Level	Temperature
-	PM6 Kirma Hydraulic (PM6KH)	----- Readings not taken -----	
-	PM6 Main Lube (PM6FH)	----- Readings not taken -----	

PM6 OILTANKS — Violated Assets

Date Time	Asset Name	Oil Level	Temperature
26/06/26 15:08	PM6 Flexo Hydraulic (PM6FH)	2	11
-	PM6 Unirun (PM6U)	----- Readings not taken -----	
-	PM6 Flexo Lube (PM6FH)	----- Readings not taken -----	

PM6 GEARBOX — Violated Assets

Date Time	Asset Name	Oil Level	Temperature
-	PM6 M704 (PM6GBM704)	----- Readings not taken -----	

PM3 OILTANKS — Normal Assets

Date Time	Asset Name	Breather Oil Leak	Oil Level
-	PM3 Flexo Hydraulic (PM3FH)	----- Readings not taken -----	
-	PM3 Flexo Lube (PM3FL)	----- Readings not taken -----	
-	PM3 Main Lube (PM3ML)	----- Readings not taken -----	
-	PM3/PM6 Pope Reel Hydraulics (PM3PRH)	----- Readings not taken -----	