

SERVICE ACKNOWLEDGMENT FORM

Customer copy



SERVICE ENTRY NO
SRF26CBE0201003

BOOKING DATE
13/7/2026, 15:01:29

CUSTOMER
Mr. Muthu karuppaiya

MOBILE / COMPANY
6383142368 · A B T BUSINESS SOLUTIONS
P...

SERVICE REFERENCE



SRF26CBE0201003



BOOKING CENTER

ZIMSON Watch Store Crosscut Road The Watch Store Since 1948

84 Cross Cut Rd Peranaidu Layout Ram Nagar Coimbatore Tamil Nadu 641012

Ph: 04224377333 Email: info@zimson.com GSTIN: —

PRODUCT INFORMATION

Brand / Model No	—	Brand Name	Omega
Brand Model	TESTING Aqua Terra 150M	Case Type	CARBON
Nature of Repair	regular	Strap / Chain Type	BI-METAL CHAIN
Back Cover / S.No	—	12 Link Chain Count	12
6 Link Chain Count	—		

REMARKS

CUSTOMER REMARKS
WATCH NOT WORKING

COMPLAINT
WATCH NOT WORKING

SERVICE INFORMATION

ESTD. DELIVERY
31/7/2026

ADVANCE PAID (INR)
INR 15000.00

EST. SERVICE COST (APPROX.)
Approx. INR 80000.00

BALANCE (EXCL. TAX)
INR 65000.00

✓ Advance collected: INR 15000.00 (Cash)

This is your service acknowledgment copy. Track live repair status using the link sent on WhatsApp.

✓ CUSTOMER SIGNATURE

✓ STORE REPRESENTATIVE