# SERVICE ACKNOWLEDGMENT FORM

Customer copy

SERVICE NO.
**SRF26CBE0201020**

BOOKING DATE & TIME
**12/10/2026, 17:21:21**

CUSTOMER
**Mr. Muthu karuppaiya**

MOBILE / COMPANY
**6383142368 · A B T BUSINESS SOLUTIONS P…**

SERVICE REFERENCE

SRF26CBE0201020

## BOOKING CENTER

**ZIMSON Watch Store Crosscut Road** The Watch Store Since 1948

84 Cross Cut Rd Peranaidu Layout Ram Nagar Coimbatore Tamil Nadu 641012

Ph: 04224377333 Email: info@zimson.com GSTIN: —

## PRODUCT INFORMATION

| | | | |
|---|---|---|---|
| Brand / Model No | — | Brand Name | **RADO** |
| Brand Model | **RADOFAMILY RADO-MODEL** | Case Type | **BIMETAL** |
| Nature of Repair | **regular** | Strap / Chain Type | **BI-METAL CHAIN** |
| Back Cover / S.No | — | 12 Link Chain Count | **12** |
| 6 Link Chain Count | **6** | | |

## REMARKS

**CUSTOMER REMARKS**
watch not working

**COMPLAINT**
watch not working

## SERVICE INFORMATION

ESTD. DELIVERY
**31/10/2026**

ADVANCE PAID
**INR 0.00**

EST. COST (APPROX.)
**INR 25000.00**

BALANCE (EXCL. TAX)
**INR 25000.00**

This is your service acknowledgment copy. Track live repair status using the link sent on WhatsApp.

**CUSTOMER SIGNATURE**

**STORE REPRESENTATIVE**