

TAX INVOICE

Service bill
Place of supply: Tamil Nadu, 625605

Invoice No	: CBE0126-27028
Invoice Date	: 03/06/2026
SR No	: SRF26CBE0101021
Invoice Type	: Service bill



CBE0126-27028



BILL FROM (SELLER)	BILL TO (CUSTOMER)
ZIMSON WATCHES 12/A OPANAKARA STREET , 100 FEET ROAD , COIMBATORE PH: 9852547856 Email: cbe01@zimson.in GSTIN: 33AAACZ0566D1ZN	Customer Name : ABT BUSINESS SOLUTION Customer ID : CUST2601001 Mobile Number : 6383142368 Email ID : sivamkarupaiya15@gmail.com GSTIN Number : 33AACA4475G1ZW Pan Number : AACA4475G Billing Address : 12/1-8, Checkadian Kovil Street T Kallipatti Periyakulam, T.Kallipatti, Theni, Tamil Nadu, 625605

PRODUCT INFORMATION			
Brand Name	: Citizen	Brand Model	: Eco-Drive Promaster
Brand / Model Number	: 12.25	Nature of Repair	: Regular
Complaint	: WATHC NOT WORKING		
Advance collected	: INR 5000.00 (UPI)		

S.No	Spare Code	Item Name	HSN/SAC Number	Price	Quantity	Gross Value
1	-	CR2016 Lithium Battery	8506900090	5,000.00	1	5,000.00
2	-	Service / repair labour	9987	3,000.00	1	3,000.00
Nine Thousand Four Hundred Forty Rupees Only					2	8,000.00

PAYMENT MODES		Gross Amount	₹ 8,000.00
Advance Amount	5,000.00	Tax Amount	₹ 1,440.00
Balance — UPI	4,440.00	Net Payable ₹ 9,440.00	
Invoice total (incl. GST)	9,440.00		

TAX SUMMARY				
Tax Description	Taxable Amount	CGST	SGST	Total
18% CGST+SGST (HSN 8506900090)	5,000.00	450.00	450.00	900.00
18% CGST+SGST (HSN 9987)	3,000.00	270.00	270.00	540.00
Total	8,000.00	720.00	720.00	1,440.00

TERMS AND CONDITIONS	
1. One year warranty applicable for battery replacement.	
2. The battery of the watch is fitted in the country of origin and therefore, may have a shorter remaining life span than that of the	
3. guarantee. The battery is not covered under the 2 year guarantee.	
4. Any damage caused to the watch, by the customer, is not covered, irrespective of how it is caused. The guarantee does not cover	
5. leather straps, glass or any other item subject to wear and tear.	
6. This guarantee shall be deemed void, should the watch have any work carried out to it by an unauthorised person.	
7. If your Watch has a screw down crown and has suffered water damage due to an unsecure crown, it will not be covered.	
8. In the event of a quality failure, Watches will, at their sole discretion, choose to either repair or replace the faulty	
9. components/watch	

Invoice generated by: STORE USER CBE
For ZIMSON WATCHES

Authorised Signatory

