SERVICE ACKNOWLEDGMENT FORM

Customer copy

SERVICE ENTRY NO
SRF26CBE0201018-ARCH-8e6e3be9

BOOKING DATE
10/10/2026, 16:17:45

CUSTOMER
Mr. Muthu karuppaiya

MOBILE / COMPANY
6383142368 · A B T BUSINESS SOLUTIONS P…

SERVICE REFERENCE

SRF26CBE0201018-ARCH-8e6e3be9

BOOKING CENTER

ZIMSON Watch Store R S Puram The Watch Store Since 1948

No 520 515 Diwan Bahadur Rd RS Puram Coimbatore Tamil Nadu 641002

Ph: 04224368111 Email: info@zimson.com GSTIN: —

PRODUCT INFORMATION

Brand / Model No	**12-233**	Brand Name	**RADO**
Brand Model	**RADOFAMILY RADO-MODEL**	Case Type	**BIMETAL**
Nature of Repair	**regular**	Strap / Chain Type	**BI-METAL CHAIN**
Back Cover / S.No	**12-233**	12 Link Chain Count	**12**
6 Link Chain Count	**6**		

REMARKS

CUSTOMER REMARKS
NOT WORKING

COMPLAINT
NOT WORKING

SERVICE INFORMATION

ESTD. DELIVERY
31/10/2026

ADVANCE PAID (INR)
INR 5000.00

EST. SERVICE COST (APPROX.)
Approx. INR 50000.00

BALANCE (EXCL. TAX)
INR 45000.00

Advance collected: INR 5000.00 (Cash)

This is your service acknowledgment copy. Track live repair status using the link sent on WhatsApp.

CUSTOMER SIGNATURE

STORE REPRESENTATIVE