SERVICE ACKNOWLEDGMENT FORM

Customer copy

SERVICE ENTRY NO
SRF26CBE0201020

BOOKING DATE
12/10/2026, 17:21:21

CUSTOMER
Mr. Muthu karuppaiya

MOBILE / COMPANY
6383142368 · A B T BUSINESS SOLUTIONS P…

SERVICE REFERENCE

SRF26CBE0201020

BOOKING CENTER

ZIMSON Watch Store Crosscut Road The Watch Store Since 1948
84 Cross Cut Rd Peranaidu Layout Ram Nagar Coimbatore Tamil Nadu 641012
Ph: 04224377333 Email: info@zimson.com GSTIN: —

PRODUCT INFORMATION

Brand / Model No	—	Brand Name	**RADO**
Brand Model	**RADOFAMILY RADO-MODEL**	Case Type	**BIMETAL**
Nature of Repair	**regular**	Strap / Chain Type	**BI-METAL CHAIN**
Back Cover / S.No	—	12 Link Chain Count	**12**
6 Link Chain Count	**6**		

REMARKS

CUSTOMER REMARKS
watch not working

COMPLAINT
watch not working

SERVICE INFORMATION

ESTD. DELIVERY
31/10/2026

ADVANCE PAID (INR)
INR 0.00

EST. SERVICE COST (APPROX.)
Approx. INR 25000.00

BALANCE (EXCL. TAX)
INR 25000.00

This is your service acknowledgment copy. Track live repair status using the link sent on WhatsApp.

CUSTOMER SIGNATURE

STORE REPRESENTATIVE