

Contoso Safety 360

<input checked="" type="checkbox"/> Hazardous Condition	<input type="checkbox"/> At Risk Behavior	<input type="checkbox"/> Safety Suggestion	<input checked="" type="checkbox"/> Safety Recognition
---	---	--	--

<input type="checkbox"/> Equipment	<input type="checkbox"/> Material Handling
<input type="checkbox"/> Slips, Trips, Falls	<input type="checkbox"/> Spill, Release, Environmental
<input checked="" type="checkbox"/> Electrical	<input type="checkbox"/> PPE
<input type="checkbox"/> Ergonomics	<input type="checkbox"/> Other Safety

<input checked="" type="checkbox"/> Significant	<input type="checkbox"/> Not Significant
---	--

Findings: Electrical wires crossing in equipment cabin rooms.
some old batteries are laying around

Suggested Solutions: Electrical technicians to tidy wires up and remove the old batteries.

Submitter: Gifti Boru

Department: Operations

Date: February 23, 2022

Owner: Altin Mali

Solutions: Set up daily check to prevent this to happen again

Target Date: February 24, 2022

Close Date: February 24, 2022

Submitter Approval: Yes