

Contoso Safety 360

<input type="checkbox"/> Hazardous Condition	<input type="checkbox"/> At Risk Behavior	<input checked="" type="checkbox"/> Safety Suggestion	<input checked="" type="checkbox"/> Safety Recognition
--	---	---	--

<input type="checkbox"/> Equipment	<input type="checkbox"/> Material Handling
<input type="checkbox"/> Slips, Trips, Falls	<input checked="" type="checkbox"/> Spill, Release, Environmental
<input type="checkbox"/> Electrical	<input type="checkbox"/> PPE
<input type="checkbox"/> Ergonomics	<input type="checkbox"/> Other Safety

<input type="checkbox"/> Significant	<input checked="" type="checkbox"/> Not Significant
--------------------------------------	---

Findings: Backup water containers have minor cracks.

Water container #12 and #15

Suggested Solutions: Call maintenance technicians to examine the problems.

Report to safety team immediately

Submitter: Dirk Fourie

Department: Operations

Date: January 5, 2022

Owner: Anisa Meta

Solutions: Replaced water containers #12 and #15

Target Date: July 10, 2021

Close Date: January 11, 2022

Submitter Approval: Yes