

Red asterisk added to all mandatory fields in all pages

Customer *

Select Customer...

Chassis No: *

Chassis No

Request No: *

Request No

Request Date: *

25/06/2023

Custom Declaration No: *

Bayan No

Custom Declaration Date: *

25/06/2023

Custom Port *

salwa

Payment Type *

Payment Card

Price: *

300

Vat Amount: *

45

Add Vehicle

< Back

VEHICLE TD0006 RESULTS



VehicleInfo



Emission



HighBeam



SideSlip



Suspension



Brake



VisuallInspection



Incomplete



Pass



Fail

< Back

Update HighBeam Level Result

Test	Limit	Value	Result
Left	Between 0 cd and 250 cd	<div>157</div>	<div>✓</div>
Right	Between 0 cd and 250 cd	<div>120</div>	<div>✓</div>

Level Input
Removed

Update



Update Suspension Level results

Test	Limit	Value	Result
Front Right	Between 30% and 100%	<input type="text" value="36"/>	
Front Left	Between 30% and 100%	<input type="text" value="68"/>	
Rear Right	Between 20% and 100%	<input type="text" value="66"/>	
Rear Left	Between 20% and 100%	<input type="text" value="69"/>	

Change the Limits Description for all tests to be more clear

Update Result

Exterior Inspection

In visual inspection Page The text color turns red when you select fail ,so it will be noticeable

Standard	Item	Technical Requirements	Result	More
SASO	1.1	Vehicle Dimensions And Weight	FAIL	▼
SASO	1.2	Vehicle Color	PASS	▼
SASO	1.3	Vehicle Identification Number	FAIL	▼

المدير الفني : عبدالحكيم البريه



**QrCode added to the report
shows report information**

TAHAQOQ Vehicle Inspection Center
Address: Alkhalidiyah , Dammam ,KSA
Phone: 0577929189
Email: info@tahaqoq.com



مركز التحقق الدولية لفحص السيارات بالدمام
العنوان: الخالدية الجنوبية، الدمام، السعودية
الهاتف: 0577929189
ايميل: info@tahaqoq.com





INTERNATIONAL CO.

رسم التصدير: TD0006

التاريخ: 24/06/2023 الموافق: هـ 6/12/1444

تقرير الفحوصات الفنية

م.	المواصفة	البند	اسم الفحص	النتائج		المطابقة
1	م ق س ١٢٨٤	1/4/6	فحص غازات العادم -اول اكسيد الكربون -غاز الهيدروكربون	اول اكسيد الكربون	هيدروكربونات جزء من المليون	PASS
				0.09 %	7 ppm	
2	م ق س ١٢٨٤	5/6	فحص استقامة وشدة شعاع الانوار	يسار	يمين	PASS
				157 cd	120 cd	
3	م ق س ١٢٨٤	2/6	فحص انحراف انزلاق العجلات م/كم	0.9		PASS
4	م ق س ١٢٨٤	7/6	فحص نظام التعليق	محور امامي يمين	محور خلفي يمين	PASS
				36 %	68 %	
				66 %	69 %	

Added two cells for left and right for high beam level results

