| Record No.   | QCD/R/06   |
|--------------|------------|
| Rev.No.      | 2          |
| Rev.Date     | 12-08-2020 |
| Register No. | E-1704     |

## **PDIR INSPECTION / TEST REPORT**

| PROJECT<br>NAME:                           | CLOSE BALL BEARING S |                                      | REPORT DATE :  | 17 - 07 - 2025   |
|--|----------------------|--------------------------------------|--|--|
| ITEM NAME :                                | 450 MM               |                                      | REPORT NO. :   | 2632   |
| PARTY NAME :                               | PARKO                |                                      |  | Ebco Pvt. Ltd.   |
| DRG. No. :                                 | QUANTITY :           | 1 Set                                | ( AN ISO 9001:2015,<br>ISO 14001:2015 &  | Survey No. 53, Hissa No. 7/3,7/4,7/2A & 7/2B<br>Gaurai Pada, Vasai (E) 401 208 |
|  |                      | ISO 45000:2018<br>CERTIFIED COMPANY) | Dist Palghar, Maharastra (INDIA) Tel.: 9152796187 / 9152796188 Email: unit1@ebco.in • Website: |  |
|  |                      |                                      |  |  |
|  |                      |                                      |  | www.ebco.in<br>CIN NO. U29299MH1973PTC016890                                   |
| PURPOSE:  New Product  New Tool  New Mould | t                    | Modified Compo                       | nent   | New Material New Source New Size   |

#### (A) VISUAL AND FUNCTIONAL INSPECTION:

**SAMPLE NO.:** II / Shipment Sample

MATERIAL: ---

| ST. No. | PARAMETER / TEST    | SPECIFICATION /<br>STANDARD | OBSERVATION / RE-<br>SULT | REMARKS        |
|---------|---------------------|-----------------------------|---------------------------|----------------|
| а       | Functionality Test  |                             | fail                      | Not Acceptable |
| b       | Final Coating Check |                             | ok                        | Acceptable     |
| С       | Locking Mechanism   |                             | ok                        | Acceptable     |
| d       | Packaging Integrity |                             | ok                        | Acceptable     |
| е       | Cycle Test          |                             | pass                      | Passed         |

### (B) DIMENSIONAL INSPECTION:

| ST. No. | DRAWING PARAME-<br>TER | SPECIFICATION | OBSERVED DIMEN-<br>SION | REMARKS    |
|---------|------------------------|---------------|-------------------------|------------|
| 1       | Previous Inspections   |               | verified                | Acceptable |
| 2       | Documentation Complete |               | yes                     | Acceptable |
| 3       | Quality Standards Met  |               | yes                     | Acceptable |
| 4       | Sample Size            | 10 units      | Inspected 5 units       | Undersize  |
| 5       | Product Type           |               | Lock                    |            |

#### **REMARK:**

Batch Number: BATCH1234
 Order Number: ORD12345
 Dispatch ID: DISP6789
 Sample Size: 5 units inspected

| Record No.   | QCD/R/06   |
|--------------|------------|
| Rev.No.      | 2          |
| Rev.Date     | 12-08-2020 |
| Register No. | F-1704     |

# PDIR INSPECTION / TEST REPORT

|  | 5) | Overall | Status: | PASS |
|--|----|---------|---------|------|
|--|----|---------|---------|------|

6) All tests completed successfully

| FINAL REMARK: |  |  |
|---------------|--|--|
|               |  |  |
|               |  |  |
|               |  |  |