




BV No. 236878

LIFTING EQUIPMENT INSPECTION REPORT	Area DAMPON	Inspection Date SEP 11, 2023		Inspection Time 14:30	Previous Sticker No. 21-6388 Issued By BV
Department / contractor SUD HJR	Equipment Number S22SJ-318	Equipment Location DAMPON		Equipment Result ☒ Pass ☐ Fail	New Sticker No. BV-21-9539
Manufacturer JLG	Model 660SJ	Capacity 500 LBS	Type MEUP	Equipment Serial Number B300002400	Sticker Expiration Date MARCH 10, 2024

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
x	Periodic inspection and function test for Boom supported structure were not performed AS per AS S. 9000 G57.034 was 92.5 "Ross" 	

RECEIVER NAME: ARJ SIGNATURE: [Signature] INSPECTOR NAME: M. J. [Signature]
BADGE#: _____ TELEPHONE NO.: _____ TELEPHONE NO.: 800 1916